

Motor- drehzahl	Kompr. Drehz. Mit 65,50=Serie	Kompr. Drehz. mit 58er=JCW	Kompr. Drehz. mit 57,00=13%	Kompr. Drehz. mit 56,50=14%	Kompr. Drehz. mit 55,50=15%	Kompr. Drehz. mit 55,00=16%	Kompr. Drehz. mit 54,50,17%	Kompr. Drehz. mit 53,70=18%	Sonstiges	
1000	2060	2327	2367	2395	2423	2452	2481	2512		
1250	2575	2909	2959	2994	3029	3065	3102	3140		
1500	3090	3491	3551	3593	3635	3678	3722	3768		
1750	3605	4073	4143	4191	4241	4291	4343	4396		
2000	4120	4655	4735	4790	4847	4904	4963	5024		
2250	4635	5237	5327	5389	5453	5517	5584	5652		
2500	5150	5819	5919	5988	6058	6130	6204	6280		
2750	5665	6400	6511	6587	6664	6744	6825	6908		
3000	6180	6982	7103	7186	7270	7357	7445	7536		
3250	6695	7564	7695	7785	7876	7970	8066	8164		
3500	7210	8146	8287	8383	8482	8583	8686	8792		
3750	7725	8728	8879	8982	9088	9196	9307	9420		
4000	8240	9310	9471	9581	9694	9809	9927	10048		
4250	8755	9892	10063	10180	10300	10422	10547	10676		
4500	9270	10474	10654	10779	10906	11035	11168	11305		
4750	9785	11056	11246	11378	11512	11648	11788	11933		
5000	10300	11638	11838	11976	12117	12261	12409	12561		
5250	10815	12220	12430	12575	12723	12874	13029	13189		
5500	11330	12801	13022	13174	13329	13488	13650	13817		
5750	11845	13383	13614	13773	13935	14101	14270	14445		
6000	12360	13965	14206	14372	14541	14714	14891	15073		
6200	12772	14431	14680	14851	15026	15204	15387	15575		
6400	13184	14896	15153	15330	15511	15695	15883	16078	Ende bei Prüfstandslauf	
6450	13287	15013	15272	15450	15632	15817	16008	16203	Drehzahlmit Automatik	
6500	13390	15129	15390	15570	15753	15940	16132	16329		
6600	13596	15362	15627	15809	15995	16185	16380	16580		
6700	13802	15595	15864	16049	16238	16430	16628	16831		
6800	14008	15827	16100	16288	16480	16676	16876	17083		
6900	14214	16060	16337	16528	16722	16921	17124	17334		
7000	14420	16293	16574	16767	16965	17166	17373	17585		
7100	14626	16526	16811	17007	17207	17411	17621	17836		
7200	14832	16758	17047	17246	17449	17657	17869	18088		
7250	14935	16875	17166	17366	17571	17779	17993	18213		